

Issues


SERVICE BULLETIN No. BB/38

- 1. WITH REFERENCE TO:** **Hot-air balloons, type BB of serial numbers 640 and higher**
- Balloons registered in the USA are not affected.
- 2. REASON:** A new revision of the Flight Manual provides better instructions for operation in windy conditions. The update and compliance with the most recent revision is highly recommended, mainly to operators who often fly in stronger wind.
- 3. REQUIRED ACTION:** Update the manual to the latest approved revision:
- Flight Manual (*doc. no. B.2102, revision 9*)
- 4. DEADLINE FOR ACTION:** **Not specified**
- 5. ACTION CARRIED OUT BY:** Owner / operator
- 6. INDUCED COST COVERED:** Owner / operator – only the cost of print
- 7. NECESSARY MATERIAL:** The above mentioned manuals
- 8. PROCESS:** Compliance with this bulletin is recommended but not mandatory. If decided to do so, download the respective document from the Kubicek Balloons website, print it and replace the manual originally supplied by the new revision.
- 9. BULLETIN TAKES EFFECT:** **29 Oct 2010**
- 10. ENCLOSURES:** None

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček, technical director



Date: **29 Oct 2010**