HOT-AIR BALLOONS & AIRSHIPS

BALÓNY KUBÍČEK spol. s r.o. • tel.: +420 545 422 620 • fax: +420 545 422 621 • info@kubicekballoons.cz • www.kubicekballoons.cz



Tssues

SERVICE BULLETIN No. BB-S/1

1. WITH REFERENCE TO: Special shaped hot-air balloons manufactured by BALÓNY KUBÍČEK spol. s r.o.:

BB ICE s/n 386, BB BEAR s/n 382, BB HEART s/n 374, BB DHL s/n 312, BB JAGER s/n 107, 138, 193, BB JAG s/n123, BB JAGER 28 s/n522, BB JUPOL s/n 130, BB KRIGL

s/n 42, 120, 185, BB BEMB s/n 116.

2. REASON: On the basis of type design rev. No. 210BB approved by EASA (no. EASA.BA.C.01101,

EASA.BA.C.01106, EASA.BA.C.01107, EASA.BA.C.01108, EASA.BA.C.01109, EASA.BA.C.01110, EASA.BA.C.01111, EASA.BA.C.01112, EASA.BA.C.01113 and

EASA.BA.C.01117) the special shaped balloon BB-S series was extended. The following special shaped balloon envelopes presently in operation in Experimental category can be transferred into BB-S type (TC No. EASA.BA.017): ICE, BEAR, HEART, DHL, JAGER, JAG,

JAGER 28, JUPOL, KRIGL, BEMB.

3. **REQUIRED ACTION:** Carry out:

- balloon inspection, replacement of the Envelope index plate / Balloon index plate and indentification marks on the envelope (in case of a re-registration under an other CAA).

- replacement / upgrade of operating documentation (Flight and Maintenance manual).

- re-registration - BB-S type family instead of Experimental cetegory.

4. DEADLINE FOR ACTION: At the latest on 23.8.2008 or till expiry of SCfA

5. ACTION CARRIED OUT: - Service organisation authorized for maintenance in accordance with Part M, section A,

head F.

- Owner / operator.

6. INDUCED COST COVERED: Owner / operator.

7. NECESSARY MATERIAL: - Flight manual B.0101 / B.0102 revision 10 including the related supplement for BB-S.

- Maintenance manual B.0201 / B.0202 revision 8.

- Envelope index plate.

- Balloon index plate (in case of a re-registration under another CAA).

- Identification marks for envelope (in case of a re-registration under another CAA).

8. PROCESS: - Carry out the envelope inspection to the extent of annual inspection according to

B.0201 / B.0202.

- Replace the index plate and possibly the Balloon index plate including fabric

identification marks on the envelope.

- Record the performed tasks into the Logbook of balloon.

- Carry out the re-registration by national CAA.

9. BULLETIN TAKES EFFECT: 17. December 2007

10. ENCLOSURES:

Technical content of this document is approved on the basis of Approval DOA No. EASA.21J.277.

On behalf of BAIÓNY KUBÍČEK spol. s r.o.

Petr Kubíček

DOA executive directo

Date: 17. December 2007