

issues

MANDATORY BULLETIN No. AB 010a

- | | |
|----------------------------------|--|
| 1. WITH REFERENCE TO: | All of the hot air balloons manufactured by 114 (714) ZO Svazarmu, Aerotechnik, Aerotechnik p.o.s. and Aerotechnik s.r.o. |
| 2. REASON: | New issue of the covering technical documentation |
| 3. REQUIRED ACTION: | Change of the Maintenance Manual concerning all translations |
| 4. DEADLINE FOR ACTION: | <ol style="list-style-type: none">1) Change the manual immediately after this bulletin receiving2) Complete the prescribed equipment before the next flight3) Carry out further technical measures resulting from this manual content, by the next prescribed inspection at the latest |
| 5. ACTION CARRIED OUT: | Balloon operator |
| 6. INDUCED COST COVERED: | Balloon operator |
| 7. NECESSARY MATERIAL: | Heat-resistant cloth (if not used as standard equipment) |
| 8. PROCESS: | <ol style="list-style-type: none">1) Cancel the present "Specification and operation and maintenance manual" in the whole range2) Replace it with new : "Maintenance Manual" (doc. No. B.0202)3) Complete the missing data on the front page (if necessary) and enter the pertinent envelope ser. No. to the line of the Registered copy No. |
| 9. BULLETIN TAKES EFFECT: | From the date of the CAA, Czech Republic approval. |
| 10. ENCLOSURES: | Maintenance Manual in the acceptable language for the operator |

On behalf of the manufacturer:

Ing. Josef Pučégl

Date: 18.10.2001