

issues

## **MANDATORY BULLETIN No. BB/14a**

1. WITH REFERENCE TO:	<ol> <li>All of the hot air balloons manufactured by 114 (714) ZO Svazarmu, Aerotechnik, Aerotechnik p.o.s. and Aerotechnik s.r.o.</li> <li>All of the hot air balloons manufactured by Kubíček spol. s r.o. and BALÓNY KUBÍČEK spol. s r.o. up to the serial number 177 incl.</li> </ol>
2. REASON:	New issue of the covering technical documentation
<b>3. REQUIRED ACTION:</b>	Change of the Maintenance Manual concerning all translations
4. DEADLINE FOR ACTION:	<ol> <li>Change the manual immediately after this bulletin receiving</li> <li>Complete the prescribed equipment before the next flight</li> <li>Carry out further technical measures resulting from this manual content, by the next prescribed inspection at the latest</li> </ol>
<b>5. ACTION CARRIED OUT:</b>	Balloon operator
6. INDUCED COST COVERED:	Balloon operator
7. NECESSARY MATERIAL:	Heat-resistant cloth (if not used as standard equipment)
8. PROCESS:	<ol> <li>Cancel the present "Specification and operation and maintenance manual" in the whole range</li> <li>Replace it for new : "Maintenance Manual" (doc. No. B.0202)</li> <li>Complete the missing data on the front page (if necessary) and enter the pertinent envelope ser. No. to the line of the Registered copy No.</li> </ol>
9. BULLETIN TAKES EFFECT:	From the date of the CAA, Czech Republic approval.
10. ENCLOSURES:	Maintenance Manual in the acceptable language for the operator
On behalf of the manufacturer: Ing. Josef Pučégl Date: 18.10.2001	BALÓNY KUBIČEK spol. sr.o.